



PipeSak® Pipeline Protection

Technical Notes

RockStop® Rockshield Storage Instructions

RockStop® ROCKSHIELD: STORAGE INSTRUCTIONS

- Maintain product packing until time of installation.
- Care should be taken when handling. Equipment forks should be routinely checked for sharp burrs and edges that may damage RockStop® rockshield.
- When storing, avoid direct contact with the ground by using appropriately sized pallets, tarp, poly, etc.
- Any damaged RockStop® rockshield should be set aside for inspection or discarded.
- Keep RockStop® rockshield dry prior to installation. Secondary tarping may be required.
- Re-cover during winter/wet installation conditions.
- Pallet covers must be replaced on partially used pallets.
- For long-term storage, protection from a secondary tarp is recommended.

RockStop® ROCKSHIELD: SAFETY RECOMMENDATIONS

- Do not attempt to lift master rolls manually, only use PipeSak® approved spreader bars.
- Ensure all associated equipment such as spreader bars, rigging and heat welding equipment are inspected daily.
- Workers must wear appropriate PPE and be vigilant toward machinery used for installation.
- Care should be taken when using heating equipment near the pipeline coating - heat must always be applied to RockStop® rockshield - not directly to the pipe.
- Do not heat RockStop® rockshield excessively. Only use a RockStop® LT Heat Tool to ensure even distribution of heat.
- Other site-specific hazards should be addressed in the field-level hazard assessment.

